

1/9




FIG. 1

2/9

200

### Real-time ShowRF

—
□
X

File Edit View Tools Help

←
→
(X)
🏠

Address

▼

(HOME) Real-time Loop Performance Analyzer (DOC)

(It takes about 20 seconds to collect data from the DSLAM. Please be patient)

202

Phone:

(format: 925-484-3260 or 9254843260)

Run Reports

Customer: **925-828-5182** DSLAM time: **2003-06-20 09:21:10**


PORT: ADSL-3-1-11-1 DSLAM: SNRMCA11H02

**Line Attributes (Doc)**

ADSLPROF	ADSLPROFN	Code	NT VPI	NT VCI	Line VPI	Line VCI	Status	STATUSNE	STATUSFE
25	384_128_fixed_basic	FAST	214	42	8	35	IS-NR	NORMAL	NORMAL
Speed (kbps)	MAXATTAINBR	MINBR	MAXBR	CURBR	PWR(dBm)	MAXAPLVL	CURPWR		
Downstream	960	384	384	384	Downstream	20	15		
Upstream	672	128	128	128	Upstream	13	2		
NMR(dB)	MINNMR	MAXNMR	TNMR	CURNMR	Others	CELLS	ATTEN(dB)	RELAP(%)	
Downstream	0	10	6	12	Downstream	42556304	55	47	
Upstream	0	10	6	18	Upstream	30760976	41	28	

204

**FIG. 2**



**FIG. 3**




FIG. 4

5/9

500

Comments

File

Edit

View

Tools

Help

←

→

X

Address

▼

Please enter comments on line 925-828-5182:

Phone:

925-828-5182

502

UserID:

bj2181

504

Comments:

506

There is a burst error on this line at 10:30 AM 6/18/03.

--rw8264 Fri Jun 20 10:34:33 PDT 2003

Clear


Send Comments

Note: The maximum comment size is 3.5KB. If the size exceeds, you need to delete the part you don't want.

**FIG. 5**




7/9




**FIG. 7**

8/9



**FIG. 8**





**FIG. 9**